



PROFIBUS DP communication module

VW3A3607

Main

Range of product Altivar

Product or component type Communication module

Complementary

Product compatibility

Range compatibility Altivar 32

Altivar Machine ATV340 except Sercos drives

Altivar Easy 610 Lexium 32

Altivar Process ATV900 Altivar Process ATV600 Altivar Machine ATV320 Altivar Process Modular

Lexium 32

Communication port protocol Profibus DP V1

Electrical connection 1 female connector SUB-D 9

Transmission rate 9.6 kbps...12 Mbps

Addressing 1...126 configurable by graphic terminal/SoMove software

Configuration settings

Communication service 4 configurable telegrams

Mapping of the process data from the master

Parameters management compliant with PROFIdrive V4.1

Several DP V1 messaging modes

Drive profile native ATV32 conforming to IEC 61800-7-201 (CiA 402)

Display type 1 LED for RUN

1 LED for bus fault (BF)

Diagnostic function Diagnostic data with VSD status

Host drive handled from two masters (MS0 and MS1) Standard identification and maintenance requests

Bus profile PROFIdrive

CiA 402

4.7 cm

Environment

Standards IEC 61800-7-201 (CiA 402)

Packing Units

Package 1 Height

Unit Type of Package 1 Db Number of Units in Package 1 1

Package 1 Width 6.1 cm

Package 1 Length	9.0 cm
Package 1 Weight	61.0 g
Unit Type of Package 2	Doboz
Number of Units in Package 2	100
Package 2 Height	30.0 cm
Package 2 Width	30.0 cm
Package 2 Length	40.0 cm
Package 2 Weight	6.798 kg

Offer Sustainability

Sustainable offer status	Green Premium product
REACh Regulation	REACh Declaration
EU RoHS Directive	Pro-active compliance (Product out of EU RoHS legal scope) EU RoHS Declaration
Mercury free	Yes
China RoHS Regulation	China RoHS declaration
RoHS exemption information	Yes
Environmental Disclosure	Product Environmental Profile
PVC free	Yes
California proposition 65	WARNING: This product can expose you to chemicals including: Lead and lead compounds, which is known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov

Recommended replacement(s)

18 months

Contractual warranty

Warranty